Jeffrey Mathis Inspection Service



502 Wharton St. Washington, NC

Prepared for: Dustin Jernigan

Prepared by: Jeffrey Mathis Inspections

163 Pond Lane

Grimesland, NC 27837

163 Pond Lane Grimesland, NC

18:56 July 01, 2015

Dustin Jernigan 502 Wharton St. Page 1 of 15

Definitions

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

Acceptable Functional with no obvious signs of defect.

Not Present Item not present or not found.

Not Inspected Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time

of inspection.

Marginal Item is not fully functional and requires repair or servicing.

Defective Item needs immediate repair or replacement. It is unable to perform its intended function.

General Information

Property Information

Property Address 502 Wharton St. City Washington State NC Zip 27889 Contact Name Amanda Hightower, United Realty

Client Information

Client Name Dustin Jernigan Client Address 1119 Bull Hill Rd. City Windsor State NC Zip 27903

Inspection Company

Inspector Name Jeffrey Mathis

Company Name Jeffrey Mathis Inspections

Address 163 Pond Lane

City Grimesland State NC Zip 27837

Phone 714-1809 Fax n/a

E-Mail jeffreymathis@embargmail.com

Amount Received \$300.00

Conditions

Others Present Buyer's Agent and Buyer Property Occupied Occupied

Estimated Age 46 yrs. Entrance Faces Street

Inspection Date 7-1-15

Start Time 3:30 End Time 5:30

Electric On Yes

Gas/Oil On Yes

Water On Yes

Temperature 90

Weather Clear Soil Conditions Dry

Space Below Grade Crawl Space

Building Type Single Family Garage None

Sewage Disposal Septic How Verified Visual Inspection

Water Source City How Verified Visual Inspection

Dustin Jernigan 502 Wharton St. Page 2 of 15

General Information (Continued)



Inspection Agreement

Inspector Name: Jeffrey Mathis

Company Name: Jeffrey Mathis Inspections

Address: 163 Pond Lane

City State Zip: Grimesland, NC 27837

Client Name: Dustin Jernigan Address: 1119 Bull Hill Rd.

City, State Zip: Windsor, NC 27903

Property Address: 502 Wharton St. City State Zip: Washington, NC 27889

InsThe Standards of Practice of the North Carolina Home Inspection Licensure Board require all inspectors to obtain a signed agreement from their clients prior to beginning the inspection.

Please assist me in conforming to state law by thoroughly reading this agreement and signing. Thank you for your cooperation.

Agreement

This company agrees to conduct an inspection at the above location for the purpose of informing the client of major deficiencies in the condition of the property. It is not meant to be a technically exhaustive evaluation. The inspection and report are performed and prepared for the sole, confidential, and exclusive use and possession of the client.

The written report will include the following:

- -structural conditions
- -general interior, including walls, ceilings, floors, windows, insulation, and ventilation
- -electrical, plumbing, water heater, heating and air conditioning
- -kitchen and appliances
- -general exterior, including roofs, gutters, chimney, drainage, and grading
- -quality condition and life expectancy of major systems

It is understood and agreed that this inspection will be of readily and safely accessible areas of the building and is limited to visual observations of apparent conditions existing at the time of the inspection only. Latent and concealed defects and deficiencies are excluded from the inspection. Equipment and systems will not be dismantled. Utilities will not be turned on.

18:56 July 01, 2015

Dustin Jernigan 502 Wharton St. Page 3 of 15

Inspection Agreement (Continued)

Maintenance and other items may be discussed but are not a part of the inspection.

This report is not a compliance inspection or a certification of past or present governmental codes or regulations.

The inspection and report do not address and are not intended to address the possible presence of or danger from any potentially harmful substances or environmental hazards including but not limited to radon gas, lead paint, asbestos, urea formaldehyde, toxic or flammable chemicals, and water or airborne hazards. We may offer or can arrange for appropriate testing as needed. Also excluded are swimming pools, wells, septic systems, central vacuum systems, water softeners, sprinkler systems, fire and safety equipment other than smoke detectors and CO detectors, and security systems. The presence of rodents, termites and other pests should be evaluated by a qualified pest contractor. If we recognize an issue regarding any of the above, we will apprise the client appropriatly.

Inspectors's Liability

The inspector will noot be responsible for any errors and ommissions unless proven to be the result of gross negligence of the said Standards of Practices of the N.C. Home Inspector Licensure Board (a copy is available upon request)

Any claimmust be presented within 30 days of the date f the inspection.

The total cost of the repairs must excees \$250.00

The repairs in question must not have been performed by another company.

Clients Claims

It is understood and agreed that should the company and/or its agents or employees be found liable or any loss or damages resulting from a failure to perform it's obligations, including to, but not limited to negligence, breach of contract, or otherwise, the liablilty of the company shall be limited to the sum equal to the amount of the fee paid by the customer for the inspection and report.

Terms

The agreed upon fee is due and payable at the time of the inspection. That fee may be deferred to closing for up to 30 days frm the date of the inspection with prior mutual agreement. Any fees not paid within 30 days are subject to a 15% interest charge.

The above terms and stipulations have been thoroughly read and understood. Jeffrey Mathis Inspection Service is hereby authorized to perform the inspection at the above property.ert your inspection agreement here.

Signature: Ou L Jum

Inspection Date: 7-1-15

Lots and Grounds

Acceptable
 Acceptable
 Acceptable
 Acceptable
 Steps/Stoops: Brick

4. Acceptable Porch: Raised brick and concrete

5. Acceptable Grading: Minor slope

6. Acceptable Swale: Adequate slope and depth for drainage

7. Acceptable Vegetation: Satisfactory

Exterior Surface and Components

All Exterior Surface

1. Marginal Type: Brick veneer - The patched cracks are in the veneer. Brick veneer is not a structural component. But if you have any concerns, they should be addressed by a licensed engineer.



Acceptable Trim: Painted cedar
 Acceptable Fascia: Aluminum
 Acceptable Soffits: Vinyl

5. Acceptable Door Bell: Hard wired

6. Acceptable Entry Doors: Wood front, metal elsewhere

7. Acceptable Patio Door: Vinyl sliding

8. Acceptable Windows: Vinyl-double hung, insulated glass9. Acceptable Window Screens: Vinyl mesh where present

18:56 July 01, 2015

Dustin Jernigan 502 Wharton St. Page 5 of 15

Exterior Surface and Components (Continued)

10. Acceptable Exterior Lighting: Surface mount11. Acceptable Exterior Electric Outlets: 110 VAC

12. Acceptable Hose Bibs: Sillcocks

13. Acceptable Gas Meter: Exterior surface mount at side of home

14. Acceptable Main Gas Valve: Located at gas meter

Roof

All inspections are performed from the ground with binoculars unless otherwise noted.

All age determinations are good faith estimates only.

All Roof Surface -

1. Method of Inspection: On roof

2. Acceptable Unable to Inspect: 0%

3. Acceptable Material: Asphalt impregnated fiberglass shingle

4. Type: Gable

5. Approx Age: 10 yrs.

6. Acceptable Flashing: Galvanized steel where visible

7. Acceptable Plumbing Vents: Cast Iron

8. Acceptable Electrical Mast: Underground utilities

Right side Chimney -

9. Acceptable
10. Acceptable
11. Acceptable
Chimney: Metal pipe
Flue/Flue Cap: Metal
Chimney Flashing: Metal

Electrical

1. Service Size Amps: 200 Volts: 110-240 VAC

2. Acceptable Service: Aluminum

3. Acceptable 120 VAC Branch Circuits: Copper

4. Acceptable
5. Acceptable
6. Acceptable
7. Acceptable
8. Acceptable
9. Acceptable
10. Conductor Type: Non-metalic sheathed cable
11. Copper and aluminum
12. Copper and aluminum
13. Copper and aluminum
14. Copper and aluminum
15. Acceptable
16. Acceptable
17. Copper and aluminum
18. Copper and aluminum
19. Copper and aluminum
10. Copper and aluminum
11. Copper and aluminum
11. Copper and aluminum
12. Copper and aluminum
13. Copper and aluminum
14. Copper and aluminum
15. Copper and aluminum
16. Copper and aluminum
17. Copper and aluminum
18. Copper an

7. Acceptable Ground: Rod in ground only.

8. Acceptable Smoke Detectors: Present near the bedrooms

Back closet Electric Panel —

18:56 July 01, 2015

Dustin Jernigan 502 Wharton St. Page 6 of 15

Electrical (Continued)

9. Marginal Manufacturer: Square D - The panel

was only partially accessible due to the shelving installed. An electrical distribution box should be fully accessible for maintenance and

examination.



10. Max Capacity: 200 Amps

11. Acceptable Main Breaker Size: 200

12. Acceptable Breakers: CU

13. Acceptable GFCI protection At the required locations

14. Is the panel bonded? Yes

Structure

1. Acceptable Structure Type: Wood frame

2. Acceptable Foundation: Brick curtain wall on concrete footings

3. Acceptable Differential Movement: No movement or displacement noted

4. Acceptable Beams: Solid wood 4x8 beams

5. Not Inspected Bearing Walls: Frame - The wall framing is not accessible for inspection.

6. Acceptable Joists/Trusses: 2x10 #2 yellow pine

7. Acceptable Piers/Posts: Concrete block

8. Acceptable Subfloor: Plywood - Under the hall bath

tub, there is evidence of previous leaking and some deteriorated

sheathing. The damaged area does not compromise the structure, but suitable

repairs are recommended.



18:56 July 01, 2015

Dustin Jernigan 502 Wharton St. Page 7 of 15

Attic

Overhead Attic •

1. Method of Inspection: In the attic

2. Acceptable Unable to Inspect: 20%

3. Acceptable Roof Framing: 2x6 rafters, 2x8 ceiling joists, 2x4 Trusses over the converted garage

4. Marginal Sheathing: Plywood - The dark plywood is a result of insufficient venting of the attic and the bath fan ducting into the attic. That creates excessive moisture and discoloration of the plywood.



5. Marginal

Ventilation: Ridge vents and soffit vents - The venting in this attic is insufficient. The gable louvers are small and the soffit venting is minimal. The fan will run excessively and the dark roof sheathing is a by-product of bad venting. Consider adding more venting both low and high.

6. Acceptable

Insulation: Fiberglass batts - The insulation levels are well below current recommended levels.

You should consider having additional insulation installed.

7. Acceptable

Insulation Depth: 4" average

8. Acceptable

Attic Fan: Direct drive Wiring/Lighting: 110 VAC lighting circuit

Acceptable
 Acceptable

Moisture Penetration: None noted

11. Marginal Bathroom Fan Venting: Ducts to the

exterior - Bathroom improperly vents

into attic and may cause moisture

damage to the insulation



18:56 July 01, 2015

Dustin Jernigan 502 Wharton St. Page 8 of 15

Crawl Space

All comments regarding bulk water or moisture intrusion are based on the visual observations that are valid only at the time of this inspection. Further observations may be necessary.

All Crawl Space -

Method of Inspection: In the crawl space
 Acceptable Unable to Inspect: 0%
 Acceptable Access: Wood door

4. Acceptable Moisture Penetration: No standing water at the time of inspection

5. Acceptable Ventilation: Vents

6. Not Present Insulation:

7. Marginal Vapor Barrier: 6 mil polyethylene plastic - The vapor barrier is damaged and incomplete. A full

and clean ground cover is a part of a good crawl space moisture control process.

Air Conditioning

Condenser at rear AC System •

Acceptable
 A/C System Operation: Adequate
 Acceptable
 Condensate Removal: PVC tubing

3. Acceptable Exterior Unit: Goodman

4. Model Number: CKL42-1L Serial Number: 05042316205. Area Served: Whole building Approximate Age: 10 yr.6. Fuel Type: 220-240 VAC Temperature Differential: 18

7. Type: Central A/C Capacity: 3.5 tons
8. Acceptable Visible Coil Aluminum
9. Acceptable Electrical Disconnect: Pull

Fireplace/Wood Stove

All inspections of chimneys are made from the firebox only.

Any concerns should be addressed by a qualified chimney technician prior to use.

Den Fireplace -

1. Marginal Fireplace Construction: Prefabricated fireplace system - Not functional.

2. Type: Vented gas logs installed.

3. Acceptable Smoke Chamber: Metal

4. Acceptable Hearth: Raised

18:56 July 01, 2015

Dustin Jernigan 502 Wharton St. Page 9 of 15

Heating System

This is a visual inspection only and no guarantee or warranty is implied or given. The inspection is valid for the above date only.

Laundry room Heating System -

1. Acceptable Heating System Operation: Adequate

2. Manufacturer: Goodman

3. Model Number: GCH950703BXAD Serial Number: 1307302607

4. Type: Gas furnace Capacity: 70,000 Btu

5. Area Served: Whole building Approximate Age: 2 yrs.

6. Fuel Type: Propane gas

7. Acceptable Heat Exchanger: 3 Burner

8. Unable to Inspect: 50%

9. Acceptable Blower Fan/Filter: Direct with disposable filter

10. Acceptable Distribution: Metal and flex duct

11. Acceptable Draft Control: Automatic12. Acceptable Flue Pipe: PVC power vent

13. Acceptable Thermostats: Single

14. Not Present

15. Suspected Asbestos: No

Plumbing

1. Not Inspected Service Line: Unknown

2. Acceptable Main Water Shutoff: At the meter

3. Acceptable Water Lines: Mix of copper, PEX, and galvanized steel

4. Acceptable Drain Pipes: Cast iron and PVC plastic - Most of the right front bathroom plumbing is not

accessible for inspection.

5. Acceptable Service Caps: accessible

6. Acceptable Vent Pipes: PVC

7. Not Inspected Gas Service Lines: Copper

Laundry room Water Heater -

8. Acceptable Water Heater Operation: Functional at time of inspection

9. Manufacturer: Whirlpool

10. Model Number: EE3J50RD045V Serial Number: 0806T438582

11. Type: Electric Capacity: 50 gallons

12. Approximate Age: 7 yrs. Area Served: Whole building

13. Acceptable TPRV and Drain Tube: CPVC

18:56 July 01, 2015

Dustin Jernigan 502 Wharton St. Page 10 of 15

Bathroom

We do not fill tubs up to or past the over-flow valves. Many older installations may leak due to worn gaskets. Some will leak due to poor installation. If this is a concern, you may wish to check further.

Right front Bathroom -

 Acceptable 	Ceiling: Drywall
2. Acceptable	Walls: Drywall
3. Acceptable	Floor: Ceramic tile
4. Acceptable	Doors: Flush wood

5. Acceptable Windows: Vinyl-double hung, insulated glass
 6. Acceptable Electrical: 110 VAC outlets and lighting circuits
 7. Acceptable Counter/Cabinet: Cultured Marble and wood

8. Acceptable Sink/Basin: Cultured marble

9. Acceptable Faucets/Traps: Faucet and PVC trap

10. Marginal Tub/Surround: Fiberglass tub/shower unit - The tub was slow to drain. If this is a concern,

have a licensed plumber evaluate and repair.

11. Acceptable Toilets: China

12. Acceptable HVAC Source: Heating system register13. Acceptable Ventilation: Electric ventilation fan

Hall Bathroom -

14. Acceptable Ceiling: Drywall
15. Acceptable Walls: Drywall
16. Acceptable Floor: Ceramic tile
17. Acceptable Doors: Flush wood

18. Acceptable Windows: Vinyl-double hung, insulated glass19. Acceptable Electrical: 110 VAC outlets and lighting circuits

20. Acceptable Sink/Basin: Pedistal type

21. Acceptable Faucets/Traps: Faucet and PVC trap, Faucet and chrome trap

22. Acceptable Tub/Surround: Cast iron and tile

23. Acceptable Toilets: China

24. Acceptable HVAC Source: Heating system register, Electric resistance heat in ceiling fan

25. Acceptable Ventilation: Electric ventilation fan

18:56 July 01, 2015

Dustin Jernigan 502 Wharton St. Page 11 of 15

Kitchen

Rear Kitchen -

1. Marginal Cooking Appliances: Whirlpool electric range - I did not get the cook-top elements to come on.

Have the seller show you how it works or have an appliance technician evaluate.

2. Acceptable Ventilator: Recirculating3. Acceptable Dishwasher: Maytag

4. Air Gap Present? Yes

5. Acceptable Refrigerator: Whirlpool6. Acceptable Sink: Stainless steel

7. Acceptable Electrical: 110 VAC outlets and lighting circuits

8. Acceptable Plumbing/Fixtures: Faucet and PVC trap

9. Acceptable Counter Tops: Laminate

10. Acceptable Cabinets: Pre-fabricated wood

11. Acceptable Ceiling: Drywall12. Acceptable Walls: Drywall13. Acceptable Floor: Laminate

14. Acceptable Windows: Vinyl, single-hung, insulated glass

15. Acceptable HVAC Source: Heating system register

Bedroom

Left front Bedroom -

Acceptable
 Doors: Flush wood

6. Acceptable Windows: Vinyl-double hung, insulated glass7. Acceptable Electrical: 110 VAC outlets and lighting circuits

8. Acceptable HVAC Source: Heating system register

Left rear Bedroom -

9. Acceptable
10. Acceptable
11. Acceptable
12. Acceptable
13. Acceptable
14. Acceptable
15. Acceptable
16. Carpet
17. Carpet
18. Acceptable
19. Closet: Single
Walls: Drywall
Floor: Carpet
Doors: Flush wood

14. Acceptable Windows: Vinyl-double hung, insulated glass15. Acceptable Electrical: 110 VAC outlets and lighting circuits

16. Acceptable HVAC Source: Heating system register

Right front Bedroom -

17. Acceptable Closet: Single
18. Acceptable Ceiling: Drywall
19. Acceptable Walls: Drywall
20. Acceptable Floor: Carpet
21. Acceptable Doors: Flush wood

18:56 July 01, 2015

Dustin Jernigan 502 Wharton St. Page 12 of 15

Bedroom (Continued)

22. Acceptable Windows: Vinyl-double hung, insulated glass23. Acceptable Electrical: 110 VAC outlets and lighting circuits

24. Acceptable HVAC Source: Heating system register

Living Space

Living Room Living Space •

Acceptable
 Acceptable
 Acceptable
 Acceptable
 Acceptable
 Acceptable
 Acceptable
 Acceptable
 Acceptable
 Doors: Solid wood

6. Acceptable Windows: Vinyl-double hung, insulated glass7. Acceptable Electrical: 110 VAC outlets and lighting circuits

8. Acceptable HVAC Source: Heating system register

Dining Room Living Space -

9. Acceptable
10. Acceptable
11. Acceptable
12. Acceptable
13. Acceptable
14. Acceptable
15. Acceptable
16. Ceiling: Drywall
Walls: Paneling
Floor: Laminate
Windows: Patio door

13. Acceptable Electrical: 110 VAC outlets and lighting circuits

14. Acceptable HVAC Source: Heating system register

Den (converted garage) Living Space -

15. Acceptable Closet: Three16. Acceptable Ceiling: Drywall17. Acceptable Walls: Paneling

18. Acceptable Floor: Carpet, Ceramic tile

19. Acceptable Doors: Flush wood

20. Acceptable Windows: Vinyl-double hung, insulated glass21. Acceptable Electrical: 110 VAC outlets and lighting circuits

22. Acceptable HVAC Source: Heating system register

18:56 July 01, 2015

Dustin Jernigan 502 Wharton St. Page 13 of 15

Laundry Room/Area

Right side Laundry Room/Area

Acceptable Ceiling: Drywall
 Acceptable Walls: Drywall

3. Acceptable Floors: Vinyl sheet goods

4. Acceptable Doors: Flush wood

5. Acceptable Electrical: 110 VAC outlets and lighting circuits

6. Not Present HVAC Source:

7. Acceptable Washer Hose Bib: sillcocks

8. Acceptable Washer and Dryer Electrical: 110-240 VAC

9. Acceptable Dryer Vent: Metal flex



Dustin Jernigan 502 Wharton St. Page 14 of 15

Marginal Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

Exterior Surface and Components

1. All Exterior Surface Type: Brick veneer - The patched cracks are in the veneer. Brick veneer is not a structural component. But if you have any concerns, they should be addressed by a licensed engineer.



Electrical

2. Back closet Electric Panel Manufacturer: Square D - The panel was only partially accessible due to the shelving installed. An electrical distribution box should be fully accessible for maintenance and examination.



Dustin Jernigan 502 Wharton St. Page 15 of 15

Marginal Summary (Continued)

Attic

3. Overhead Attic Sheathing: Plywood - The dark plywood is a result of insufficient venting of the attic and the bath fan ducting into the attic. That creates excessive moisture and discoloration of the plywood.



4. Overhead Attic Ventilation: Ridge vents and soffit vents - The venting in this attic is insufficient. The gable louvers are small and the soffit venting is minimal. The fan will run excessively and the dark roof sheathing is a by-product of bad venting. Consider adding more venting both low and high.

5. Overhead Attic Bathroom Fan Venting: Ducts to the exterior - Bathroom improperly vents into attic and may cause moisture damage to the insulation



Crawl Space

6. All Crawl Space Vapor Barrier: 6 mil polyethylene plastic - The vapor barrier is damaged and incomplete. A full and clean ground cover is a part of a good crawl space moisture control process.

Fireplace/Wood Stove

7. Den Fireplace Fireplace Construction: Prefabricated fireplace system - Not functional.

Bathroom

8. Right front Bathroom Tub/Surround: Fiberglass tub/shower unit - The tub was slow to drain. If this is a concern, have a licensed plumber evaluate and repair.

Kitchen

9. Rear Kitchen Cooking Appliances: Whirlpool electric range - I did not get the cook-top elements to come on. Have the seller show you how it works or have an appliance technician evaluate.